DAIMLER TRUCK

Financial Services



Fair valuation for trucks.

Information about vehicle return from leasing and Service-Leasing.



Contents

/aluation guidelines	4
Examples of damage assessment	
Bumpers, wheel cover, entrance	5
Cargo liftgate, box body, mirrors	6
Door, rear of cab, body interior	7
Frame cover, side impact protection, wings	8
Instrument panel, seats, tank	9
Wind deflectors, spoiler, side protection cladding	10
Attachments and conversions	11
Stone chipping on windscreen	13
Statutory inspections and maintenance services	16
Battery in electric vehicles	17



Your satisfaction is particularly important to us.

Daimler Truck Financial Services Deutschland GmbH will provide you with your individual vehicle for the contractually agreed service life. During this period of use, the specified residual value of your truck and its individual body is guaranteed subject to careful use and maintenance of the vehicle

If you return your vehicle to your Mercedes-Benz or FUSO dealership or TruckStore at the end of your contract, Daimler Truck Financial Services Deutschland GmbH will always commission an independent expert report at its own expense, which is used to assess and evaluate your returned vehicle according to specified standards.

With this brochure, we would like to prepare you for the return of your Mercedes-Benz truck or FUSO Canter from leasing or Service-Leasing and provide you with important information beforehand to ensure a fair and transparent vehicle valuation. If your dealership has guaranteed the residual vehicle value to Daimler Truck Financial Services

Deutschland GmbH, an independent expert report will only be commissioned after prior agreement between you and your dealership.

Valuation guidelines for vehicle return.

There is a differentiation between three types of damage in the vehicle valuation:

Signs of use are caused by the intended use of the vehicle and are free of charge.

Impact damage extends beyond normal wear and tear and results from negligent use. The rectification of the damage is subject to a charge.

Technical damage to the vehicle such as engine, transmission, air conditioning system etc. are subject to a charge.

When assessing the depreciation which the customer must compensate for, the age of the vehicle and the mileage are considered in each case.

One exception concerns Service-Leasing contracts. In this case, technical damage is covered in accordance with the scope of the contract.

You will find information for damage assessment on the following pages.

The overview does not claim to be complete. The examples are categorised as follows for your information.



Free of charge

Signs of use



Subject to a charge

- Impact damage
- Technical damage

Examples of damage to bumper, wheel cover, entrance.






Bumpers/signs of useMinor scuffing





Wheel cover/signs of use

Minor scratches and pressure marks





Entrance/signs of use

Minor scrapes





Bumpers/impact damage

 Major scrapes, crack formation or material fractures





Wheel cover/impact damage

• Holes or deformations





Entrance/impact damage

• Deep scratches, material ablation or crack formation

Examples of damage to cargo liftgate, box body, mirrors.





Cargo liftgate/signs of use

• Minor scrapes in paint, typical signs of wear





Box body/signs of use

Scratches caused by scraping





Mirrors/signs of use

Minor scrapes





Cargo liftgate/impact damage

• Material deformations, fractures





Box body/impact damage

 Major scrapes in the paintwork, down to the primer





Mirrors/impact damage

Deep scratches, crack formation or material chipping

Examples of damage to door, rear of cab, interior body.









Door/signs of useMinor scratches



Rear of cab/signs of use

 Minor scratches, small dents or chafe marks



Interior body/signs of use

Minor dents without cracks







(x)

Door/impact damage

Major damage to the paintwork



Rear of cab/impact damage

Dents, damage to paintwork, dented or cracked



Interior body/impact damage

• Deep dents with cracks or puncture in the box body insulation

Examples of damage to frame cover, side impact protection, wings.









Frame cover/signs of use

• Minor deformations, minor scratches



Side impact protection/signs of use

Minor scrapes



Wings/signs of use

Minor surface scratches









Frame cover/impact damage

Major deformations

Side impact protection/impact damage

Major deformations





Wings/impact damage

• Scratches, crack formation or material chipping

Examples of damage to instrument panel, seats, tank.













Instrument panel/impact damageDeep scratches, holes or boreholes



Seats/impact damage

• Holes or cracks



Tank/impact damage
• Deformations

Examples of damage to wind deflectors, spoiler, side protection cladding.







Spoiler/signs of use • Damage to paintwork



Side protection cladding/signs of use Minor scrapes



Wind deflector/impact damage • Scratches, cracks or fractures



Spoiler/impact damage

Side protection cladding/impact damage

• Scratches, cracks or fractures



· Scratches, cracks or fractures


Examples of damage to attachments, bodies and conversions.





Box body/impact damage

• Box body with polystyrene plates and water heater removed





Spoiler/impact damage

- Lighting retrofitted
- Not installed professionally
- Loose cable connection





Lamp bracket/impact damage

- Not installed professionally
- Water ingress
- Lamp bracket non-functional

Examples of damage to attachments, bodies and conversions.





Lamp bracket/signs of use

- No depreciation
- Functional
- Professional installation





Auxiliary air conditioning system/signs of use

- No depreciation
- Functional
- Professional installation






Rotating beacon/signs of use

- No depreciation
- Functional
- Professional installation

Examples of damage to a windscreen caused by stone chipping.






Stone chipping outside of the driver's field of vision

- Stone chipping up to max. Ø 2.5 cm (2 euro coin)
- Outside of the edge area (approx. 10 cm)

Repair is required.



- Stone chipping larger than Ø 2.5 cm (2 euro coin)
- Within the edge area (approx. 10 cm)
- In the event of crack formation, also outside of the field of vision
- Scratches on the windscreen

Repair is not possible, windscreen replacement is required.

Examples of damage to a windscreen caused by stone chipping.





Stone chipping/impact damage

- Stone chipping with crack formation
- Outside of field of vision
- Repair is not permitted
- Windscreen replacement





Stone chipping/impact damage

- Stone chipping without crack formation
- Within the field of vision
- Repair is not permitted
- Windscreen replacement

Examples of damage to a windscreen caused by stone chipping.





Scratches/impact damage

- Windscreen scratched
- Repair is not permitted
- Not HU-capable
- Windscreen replacement





Stone chipping/impact damage

- Stone chipping without crack formation
- Outside of field of vision
- Repair is permitted
- Smart Repair

Examples of damage for statutory inspections and maintenance services.

- Maintenance services currently due*
- Statutory inspections expired* (main inspection, emissions inspection, accident prevention regulations, §57B)
- Tyre tread depth less than 6 mm
- Retreaded tyres on steering and trailing axles
- Regrooved tyres on every axle
- Retreaded tyres on the drive axle
- Active fault message

*In the case of a valid Service Complete contract, the costs are settled as part of this contract (no costs for the customer)

Examples of damage to batteries in electric vehicles.

The following additionally apply to electric vehicles Valuation criteria:

- Mechanical damage to the battery housing (dents, cracks, etc.), especially on the underbody
- Maintenance intervals were not fully complied with (e.g. coolant, replacement of drier cartridge)
- Recognisable, undocumented repair measures



